

Alcohol Countermeasure Systems Corp

60 International Boulevard Toronto, Ontario M9W 6J2 CANADA

T +1 416 619 3500 F +1 416 619 3501

info@acs-corp.com acs-corp.com

ACS, ALCOHOL COUNTERMEASURE SYSTEMS, ALCOLOCK, INTERTRACK and the "Molly" are trademarks of Alcohol Countermeasure Systems (International) Inc. and are used under license. Alcohol Countermeasure Systems is the trading style of Alcohol Countermeasure Systems Corp.

All content in this document, inclusive but not limited to the text, images and trademarks mentioned therein, is owned by Alcohol Countermeasure Systems (International) Inc. ["ACS"] and used under license by its affiliated companies. All copyright and other proprietary rights to this content are reserved. No reproduction of this document, in whole or in part, is permitted without the prior written consent of ACS.

This document, and the content contained therein, can be used only for purposes relating to the ALCOLOCK™ ignition interlock program.

While reasonable efforts are made to ensure that the contents of this document are accurate, this document is provided on an "as is," "as available" basis, without warranties of any kind, including any warranties of accuracy. Because some jurisdictions do not permit the exclusion of certain warranties, these exclusions may not apply to you. In no event will ACS or its affiliates be liable for any incidental, indirect, consequential, or special damages of any kind, or any damages whatsoever arising out of or in connection with the use of this document or its contents.

The ALCOTRACK[™] platform contains personal information. Unauthorized release of personal information can result in civil and criminal liability. By using the ALCOTRACK platform, you accept your responsibility to refrain from any use or disclosure of the personal information contained in the ALCOTRACK[™] platform otherwise than as required as part of your employment or otherwise required by law. **Keep your login credentials confidential**.

©2017 Alcohol Countermeasure Systems

The information disclosed in this document is the valuable property of Alcohol Countermeasure Systems and all copyright and other proprietary rights to this document are reserved. No reproduction of this document is permitted without the prior written consent of Alcohol Countermeasure Systems.

1. Complete a *Monitor* procedure in ALCOTRACK and on the handset.

- C A	cohol CounterMeasure !	ystems Corp [CA] https://n2.felcor	ncorp.com/alcolock/Prog	ram/ViewProgram/03200	0102000005				☆ 問
A	lcoTrack~ ™	nu -			English (E	spañol	My Settings L	og out	Manual -	
Pro	gram									
Se	arch Client View C	onnected	Back					001 (ALCOLO	CK MD Inc) +	
		Client		Program Id	Category, Device	Status	Install Anticipated End	Paid To		
			ND, Alcolock Agreement	03200102000005 2012 FORD F250	Private, LR	Active	09-14-2017	09-19-2017	1	
-	a contraction of the second	/pe	Date Time	Amount	Previous Account	New Acco			_	
	03200103000039 N	onitor	09-14-2017 1	1:45:44	-2.79 Internal Notes 2017)	: test (Goodwin,	-0.17 Chad 09-14-			
	03200103000038 \$	ale	09-14-2017 1	3:44.06	-0.17		-2.79			
					Internal Notes 2017)	: test (Goodwin,	Chad 09-14-			
	03200103000037	alibration	09-14-2017 13	3.38.08						
	03200103000036 In	stall	09-14-2017 1	3 26 58	-13.24		-0.17			
					Internal Notes 2017)	: test (Goodwin,	Chad 09-14-			
	03200103000035 \$	ale	09-14-2017 13	3:23:45	-2.79		-13.24			
					Internal Notes 14-2017)	alc test (Good)	vin, Chad 09+			

2. Click the Pencil icon to create a new transaction.


Alcohol CounterMeasure Systems	Corp [CA] https://n2.felct	emeorp.com/alcolock/Prog	ram/ViewProgram/03200	0102000005			
AlcoTrack~ Menu -			English E	spañol (My Settings I	Log out 1	Manual -
Program							
Search Client View Connecte	d Back					001 (ALCOLOCK	MD Inc) +
ci	ent	Program Id	Category, Device	Status	Install Anticipated End	Paid To	
	RYLAND, Alcolock rvice Agreement	03200102000005 2012 FORD F250	Private, LR	Active	09-14-2017	09-19-2017	1
Transaction Id Type	Date Time	Amount	Previous Account	New Acco	unt		
C3200103000039 Monitor	09-14-2017	13:45:44	-2.79		-0.17		
			Internal Notes 2017)	: test (Goodwin,	Chad 09-14-		
03200103000038 Sale	09-14-2017	13:44:05	-0.17		-2.79		
			Internal Notes 2017)	: test (Goodwin,	Chad 09-14-		
03200103000037 Calibratio	09-14-2017	13:38:08					
03200103000036 Install	09-14-2017	13:26:58	-13.24		-0.17		
			Internal Notes 2017)	: test (Goodwin,	Chad 09-14-		
03200103000035 Sale	09-14-2017	10.00.10	-2.79		-13.24		

3. In the Service Group field, select Handset from the drop-down menu.

C Alcohol Co	ounter/Measure Systems Corp [CA] https://n2.felcomcorp.com/alcolock/Program	m/YiewProgram/03200102000005	☆ []
AlcoT	rack Menu -	English (Español) My Settings (Log out) Manual -	
Program	Create Transaction		
	Service Type Products Payment	001 (ALCOLOCK MD Inc)	
	Client MARYLAND, Alcolock	Program Id 0320010200005	
	Current Paid To 09-19-2017	Opening Account -0.17	
	Service Group	Service Type	
	Monitor 🗸	Monitor	
	Install Montor	Time *	
	EOP Handset Others	09:00	
	Next Step Cancel		

4. In the Service Type field, select Handset Return from the drop-down menu.

Alco	Track Menu -	English Español My Settings Log out Ma	+ Isun
Program	n: Create Transaction		
	Service Type Products Payment	001 (ALCOLOGK MD Inc)	
	Client MARYLAND, Alcolock	Program Id : 03200102000005	
	Current Paid To 09-19-2017	Opening Account -0.17	
	Service Group	Service Type	
	Handset	V Handset Return V	
		Handset Exchange Handset Return	



6. In the Internal Notes field, enter "Calibrated HS Exchange".

				¢			
Service Type Products Payment		001 (ALCOLOCK MD Inc)					
Client MARYLAND, Acolock	Program Id 03200102000005						
Current Paid To 09-19-2017	Opening Account -0.17						
New Paid To 09-19-2017	Service Type Handset Return						
Product Type Service/Accessory Discount C Refund V3/Drive	Add Product		~				
Product	Quantity	Price	Total				
		Subtotal	0				
Remarks Covernment	Comments Internal No	tes					
	Calibrate H	S Exchange					
A			A				

C Alcoho	I CounterMeasure Systems Corp [CA] https	c/nZ.telcomcorp.com/alcolock/Prog	ram/ViewiProgram/05200				Ŷ	問
	Service Type Products F	Payment			001 (ALCOLO	CK MD Inc)		
	Client		Program Id					
	MARYLAND, Alcolock		03200102000005					
	Current Paid To 09-19-2017		Opening Account -0.17					
	New Paid To		Service Type					
	09-19-2017		Handset Exchange					
	Product Type		Add Product					
	Service/Accessory Discourt	nt 🔍 Refund 🔍 V3/Drivesafe				~		
	Product			Quantity	Price	Total		
	ALCOLOCK™ LR PROGRAM FEE	£		0	2.4658	0.00		
					Subtotal	0		
					Total	0		
	Remarks	Government Comme	ints	Internal Notes				
	2			Calibrated Han	dset Exchange			

8. Select Complete.

Program: Cr	eate Transaction						
	Service Type Products	Payment			001 (ALCOLO	CK MD Inc)	
	Client MARYLAND, Alcolock Current Paid To 09-19-2017		Program Id 05200102000005 New Paid To 09-19-2017				
	Service Type Handset Return		Next Service Type Handset Exchange			~	
	Odometer		L				
	0						
	Product			Quantity	Price	Total	
					Subtotal	o	
					Total	0	
			Opening Account -0.17	Amount: 0	New Act	count: -0.17	
	Previous Step Complete	Cancel					

9. Plug in the handset. In ALC, once the client information appears, select the Handset Return icon.

ALCOLO	CK Communicator [Cl	nad Goodwir	1]				X
Eile Servic	e Se <u>t</u> tings <u>V</u> iew	Help					
	n 7 7 1	í 🖱 🖻	r 🕯 🗎	Å	C		
Service	Calibration					Location: 032001	- ALCOLOCK MD Inc
Program:	03200102000005				_		
First Name:	Alcolock						
Last Name:	MARYLAND				_		
Make:	FORD						
Plate:	VTG1234						
	erial: 0012412 Firmw	are: 02.15 (Event log: Ready	
USD: LK :	enal: 0012412 Firmw	are: 05.15 (-)	_		Eventiog: Ready	

10. A pop up will appear asking "Do you wish to Continue?". Select OK.

ALCOLO	CK Communicator [Chad Goodwin]	
<u>File</u> Servic	e Se <u>t</u> tings ⊻iew <u>H</u> elp	
A A	n 2244 51 57 6	
Service	Calibration	Location: 032001 - ALCOLOCK MD Inc
Program:	03200102000005	
First Name:	Alcolock	
Last Name:	MARYLAND	
Make:		2000005
Plate:	VTG1234 Handset Return - Program 03200102	2000005
		Canod
USB: LR	Gerial: 0012412 Firmware: 03.15 ()	Event log: Ready

11. Once the handset beeps twice, click Close. Disconnect the handset.

ALCOLOCK Communicator [Chad Goodwin]	
Eile Service Settings View Help	
Service Calibration Loc	ation: 032001 - ALCOLOCK MD Inc
Service completed - Disconnect Handset Handset Return - Program 03200102000005 Saving event log OK Setting Handset date and time OK Charing event log OK Dealing event log OK Praising service OK Praising service OK Provide Completed Service completed	
USB: LR Serial: 0012412 Firmware: 03.15	

12. Connect the new handset to the download station. In ALCOTRACK, click the Pencil icon to create a new transaction.

Alcohol CounterMeasure Sy	stems Corp (CA)	https://n2.felcom	corp.com/alcolock/Prog	ram/ViewProgram/03200	102000005			
AlcoTrack [™] Mer	u •			English E	spañot j	My Settings	Log out	Manual =
Program								
Search Client View Co	nnected	Back					001 (ALCOLO	CK MD Inc) •
	Client		Program Id	Category, Device	Status	Install Anticipated End	Paid To	
	MARYLAND, Service Agree		03200102000005 2012 FORD F250	Private, LR	Active	09-14-2017	09-19-2017	
Transaction Id Ty		Date Time	Amount	Previous Account	New Acco	unt		
B 03200103000039 Md	nitor	09-14-2017 13	45:44	-2.79		-0.17		
				Internal Notes 2017)	test (Goodwin,	Chad 09-14-		
03200103000038 Sa	e	09-14-2017 13	44:05	-0.17		-2.79		
				Internal Notes 2017)	test (Goodwin,	Chad 09-14-		
03200103000037 Ca	ibration	09-14-2017 13	38:08					
03200103000036 Ins	tall	09-14-2017 13	26.58	-13.24		-0.17		
				Internal Notes 2017)	test (Goodwin,	Chad 09-14-		
	e	09-14-2017 13		-2.79		-13.24		

13. In the Service Group field, select Handset from the drop-down menu.

e - c 🔹	Alcohol CounterMeasure Systems Corp [CA] https://n2.felcomcorp.com/alcolock/Program	n/ViewProgram/03200102000005	\$ 11.3
,	AlcoTrack~ Menu -	English Español My Settings Log out Manual -	
P	Program: Create Transaction		
	Service Type Products Payment	601 (ALCOLOCK MD Inc)	
	Client MARYLAND, Alcolock	Program Id 03200102000005	
	Current Paid To	Opening Account	
	09-19-2017 Service Group	-0.17 Service Type	
	Monitor	Monitor	
	Install Monitor	Time *	
	EOP	09:00	

14. In the Service Type field, select Handset Exchange from the drop-down menu. Ensure that the *Next Service Date* and *Time fields* are correct. In the *Exchange Reason* field, select "HS Repair".

AlcoTr	ack™ Menu -	English Español My Settings Log out Manual +	
Program: 0	Create Transaction		
	Service Type Products Payment	001 (ALCOLOCK MD Inc)	
	Client MARYLAND, Alcolock	Program Id 03200102000005	
	Current Paid To 09-19-2017	Opening Account -0.17	
	Service Group	Service Type	
	Handset	Handset Exchange	
	Next Service Date * Scheduler Assistant	Time *	
	09-19-2017	09:00	
		Exchange Reason *	
		HS Repair HS Service/No Vehicle	

٨	lcoTrack™ Menu -	English Español My Settings Log out Manual	
~	icoli dek		
Pro	gram: Create Transaction		
	Service Type Products Payment	001 (ALCOLOCK MD Inc)	
	Client MARYLAND, Alcolock	Program Id 05200102200005	
	Current Paid To 09-19-2017	Opening Account -0.17	
	Service Group Handset	Service Type Handset Exchange	
	Next Service Date * Scheduler Assistant	Time *	
	09-19-2017	09:00	
		Exchange Reason *	
		HS Repair HS Service/No Vehicle	

16. In the Internal Notes field, enter "Calibrated Handset Exchange".

Service Type Products Payment	001 (ALCOLOCK MD Inc)	
Client	Program Id	
MARYLAND, Alcolock	03200102000005	
Current Paid To	Opening Account	
09-19-2017	-0.17	
New Paid To	Service Type	
09-19-2017	Handset Return	
Product Type	Add Product	
* Service/Accessory © Discount © Refund © V3/Drivesafe	~	
Product	Quantity Price Total	
	Subtotal 0	
	Total 0	
Remarks Government Comm	nts Internal Notes	
	Calibrate HS Exchange	
A		

← → C · Alcohol	CounterMeasure Systems Corp (CA) https://n2.felcomcorp.com/alcolock/Progr	ram/ViewProgram/03200102000005			☆ Ⅲ	1
	Service Type Products Payment		001 (ALCOLO	CK MD Inc)		1
	Client NARYLAND, Arcelock Current Paid To 03-15-2017 New Paid To 05-19-2017 Product Type	Program 1d 03200102000005 Opening Account -0.17 Service Type Handset Return Add Product				
	Service/Accessory Discount Refund V3/Drivesafe	Add Product		~		
	Product	Quantity	Price	Total		1
			Subtotal	0		
			Total	0		1
	Remarks Government Comme	internal Notes				
		Calibrate HS Ex	Calibrate HS Exchange			1
	Previous Step Next Step Cancel					ļ

18. Select Complete.

Program: C	reate Transaction						
	Service Type Products	Payment			001 (ALCOLO	CK MD Inc)	
	Client MARYLAND, Alcolock		Program Id 05200102000005				
	Current Paid To 09-19-2017		New Paid To 09-19-2017				
	Service Type		Next Service Type				
	Handset Exchange		Monitor			~	
	Product			Quantity	Price	Total	
	ALCOLOCK™ LR PROGRAM	FEE		0	2.4658	0.00	
					Subtotal	0	
					Total	0	
			Opening Account: -0.17	Amount: 0	New Ac	count: -0.17	
	Previous Step Complete	Cancel					

19. Plug in the handset. In ALC, confirm that the correct client information is highlighted, and select the Handset Exchange icon.

le Service	Settings	View H	elp						
A A 16	() 영상	5 M	# B		& C				
Service	Ca H	landset Exc	hange					Location: 032001 - ALC	OLOCK MD
Program: 0	13200102000	005							
First Name: A	Ncelock				_				
ast Name: M	MARYLAND			_					
Make: Fi	FORD				_				
Plate: V	/TG1234								
		exchange :	vervice						
Select vehicle rogram 🐱	e for Handaet	First Name		 d Name		Make	Plate	Service T	
elect vehicle ogram 🗸	e for Handaet			 d Name	0	Make FORD	Plate VIG1234	Service T Handaet E	
nlect vehicle ogram 🛩	e for Handaet	First Name			2				
nlect vehicle ogram 🛩	e for Handaet	First Name			2				
nlect vehicle ogram 🛩	e for Handaet	First Name			b				
elect vehicle ogram 🗸	e for Handaet	First Name			9				
elect vehicle	e for Handaet	First Name			9				
elect vehicle ogram 🗸	e for Handaet	First Name			2				

20. A pop up will appear asking "Do you wish to Continue?". Select OK.

	gs <u>V</u> iew <u>H</u> elp	where the second		
	A DATE OF A DATE	8104	6	
	albration			Location: 032001 - ALCOLOCK MD Ir
Program: 0320010	000005			
Rest Name: Alcolock				
Last Name: MARYLA	ND			
Make: FORD Plate: VTG1234		Handset Exchange - Pr	rogram 03200102000005	
Select vehicle for Han rogram 🕓 3200102000005	føet exchange servic First Name Alcolock		continue?	Service Type Handeet Exchange

21. Once the handset beeps twice, click Close. Disconnect the handset.

ALCOLOCK Communicator [Chad Goodwin]	
ile Service Settings View Help	
nam Ara bi df C	
Service Calibration	Location: 032001 - ALCOLOCK MD Inc
Service completed - Deconnect Hander Handsert Exchange - Program 03200102000005 Hand service: 2017-09-19 09 00 00 Sering Vander date and time. OK Sering Vander date and time. OK Georg event toOK Cereng event toOK Service completed	

